

County Name	Project Name	Construction Code Name	Route	Sub-Route	Start Mile Point	End Mile Point	Miles
Barbour	PHILIPPI BYPASS BRIDGE	Renovate	250	0	0	0.82	0.82
Berkeley	NORMAN A & CARRIE G SILVER MEMORIAL BRIDGE	Replace Bridge (Added Capacity > 12')	7	0	5.899	5.915	0.016
Berkeley	NEW GM ACCESS ROAD BR	Repair Substructure	9	30	0.109	0.126	0.017
Berkeley	SEWAGE TREATMENT PLANT BRIDGE	Replace Superstructure	683	0	0.619	0.625	0.006
Boone	TWILIGHT BRIDGE	Replace (due to condition with no added capacity <12')	26	0	6.49	8.49	2
Boone	WHITESVILLE MABEY TRUSS	Replace (due to condition with no added capacity <12')	609	0	0.021	0.049	0.028
Braxton	KENTON MEADOWS SR BRIDGES NB & SB	Renovate	79	0	51.47	51.62	0.15
Braxton	KENTON MEADOWS SR BRIDGES NB & SB	Renovate	79	0	51.558	51.706	0.148
Braxton	LEFT FORK HOLLY RVR TRUSS DEMO	Other Bridge Work	4	0	6.663	6.667	0.004
Brooke	BUFFALO CREEK BR	Renovate	67	0	0.62	0.68	0.06
Brooke	LOG CABIN BR	Replace (due to condition with no added capacity <12')	1	3	0.29	0.302	0.012
Brooke	VETERANS MEM BR	Strengthen Substructure or Superstructure	22	0	0	0.271	0.271
Cabell	WILLIAM TURMAN BRIDGE	Repair or Replace Expansion Joints	60	0	11.51	12.37	0.86
Cabell	WHITAKER BLVD BRIDGE	Replace (due to condition with no added capacity <12')	3276	0	0	1.78	1.78
Cabell	MAYOR PAUL L. TURMAN BRIDGE	Replace or Renovate Deck	1542	0	0.14	0.17	0.03
Cabell	BRYAN CREEK BEAM SPAN	Replace (due to condition with no added capacity <12')	1	11	9.731	9.737	0.006
Cabell	MASSEY FERGUSON BRIDGE	Major Superstructure Repair	10	0	0	1	1
Cabell	HEATH CREEK SLAB +2	Replace (due to condition with no added capacity <12')	10	0	6.995	7.001	0.006
Cabell	HEATH CREEK SLAB +2	Replace (due to condition with no added capacity <12')	10	0	7.13	7.14	0.01
Cabell	HEATH CREEK SLAB +2	Replace (due to condition with no added capacity <12')	10	0	7.95	7.96	0.01
Cabell	NICK JOE RAHALL BRIDGE	Strengthen Substructure or Superstructure	52	0	0	0.319	0.319
Cabell	CR 15 OP EB	Repair or Replace Expansion Joints	64	0	27.07	27.07	0
Cabell	12TH STREET BRIDGE	Replace (due to condition with no added capacity <12')	3283	0	0	0.3	0.3
Cabell	BEECHWOOD STREET BRIDGE	Replace Superstructure	1087	0	0.512	0.52	0.008
Clay	PIERSON LUMBER BRIDGE	Replace (due to condition with no added capacity <12')	16	0	16.915	18.28	1.365
Clay	O'BRION CREEK BRIDGE	Replace (due to condition with no added capacity <12')	44	0	0	3	3
Doddridge	CARR I-BEAM	Replace (due to condition with no added capacity <12')	20	0	3.83	5.04	1.21
Doddridge	SPC JASON N MARCHAND MEMORIAL BRIDGE EB & WB	Renovate	50	0	5.61	5.63	0.02
Doddridge	MILETUS I-BEAM	Replace (due to condition with no added capacity <12')	48	0	0	3.47	3.47
Doddridge	SPC JASON N MARCHAND MEMORIAL BRIDGE EB & WB	Renovate	50	0	5.633	5.655	0.022
Fayette	SMITHERS CREEK BRIDGE	Replace or Renovate Deck	2	0	0.09	0.766	0.676
Fayette	SGT SCOTT ANGEL MEMORIAL BRIDGE	Repair Substructure	60	0	10.55	10.625	0.075
Fayette	FREEWILL LANE BRIDGE	Major Superstructure Repair	1261	0	0.128	0.132	0.004
Fayette	STADIUM DRIVE BRIDGE	Replace (due to condition with no added capacity <12')	1147	0	0.056	0.062	0.006
Fayette	ARMSTRONG CREEK BRIDGE	Replace (due to condition with no added capacity <12')	61	0	27.8	27.82	0.02
Fayette	DUNLOUP CREEK BRIDGE #9	Replace (due to condition with no added capacity <12')	25	0	2.332	7.65	5.318
Gilmer	BUTCHERS RUN TRUSS	Replace (due to condition with no added capacity <12')	17	8	0	0.08	0.08
Gilmer	DUSKCAMP CHANNEL BEAM	Replace (due to condition with no added capacity <12')	42	0	3.93	6.24	2.31
Gilmer	SPRUCE RUN CONCRETE BOX	Drainage/Box Culvert	17	0	6.12	8.71	2.59
Grant	JORDAN RUN BRIDGE	Replace (due to condition with no added capacity <12')	28	7	2.88	2.92	0.04
Grant	RT 93 SCHERR STRUCTURE	Replace (due to condition with no added capacity <12')	93	0	9.71	13.436	3.726
Grant	MEDLEY BR	Replace (due to condition with no added capacity <12')	5	0	2.55	11.46	8.91
Greenbrier	LITTLE SEWELL CREEK BRIDGE	Repair Substructure	60	0	1.15	1.8	0.65
Greenbrier	TUCKAHOE RUN BRIDGE	Repair Substructure	50	0	2.1	4.07	1.97

Greenbrier	WADES CREEK BRIDGE	Replace Superstructure	548	0	0.039	0.045	0.006
Greenbrier	LITTLE ROARING CREEK BRIDGE (COLD KNOB RD)	Replace Superstructure	10	1	0.071	0.077	0.006
Hampshire	SEDAN BRIDGE	Replace (due to condition with no added capacity <12')	29	0	8.674	8.716	0.042
Hampshire	JUNCTION BRIDGE	HMA Overlay	50	0	1.58	2.12	0.54
Hancock	NORTH FORK TOMLINSON RUN BR	Replace (due to condition with no added capacity <12')	12	0	2.32	2.325	0.005
Hancock	FILMORE STREET BRIDGE	Renovate	308	0	0.067	0.067	0
Hancock	WEIRTON STEEL OVERPASS	Replace Superstructure	2	0	1.137	1.407	0.27
Hancock	WEIRTON STEEL OVERPASS	Replace Superstructure	2	0	1.09	1.137	0.047
Hardy	RIGGLEMAN ARCH	Replace (due to condition with no added capacity <12')	7	0	16.64	17.94	1.3
Hardy	HALTERMAN HOLLOW BRIDGE	Renovate	259	0	0	6.94	6.94
Hardy	DURGON STORE BRIDGE	HMA Overlay	220	0	0.28	4.17	3.89
Hardy	USAF AIRMAN 1ST CLS WILBUR LEE CLAYTON MEM BRG	HMA Overlay	48	0	9.33	19.06	9.73
Harrison	RACCOON CREEK SLAB	Replace Superstructure	20	0	2.05	2.056	0.006
Harrison	VIRGINIA AVENUE BRIDGE	Replace (due to condition with no added capacity <12')	24	0	0	0.85	0.85
Harrison	BROWNS CREEK BRIDGE NB & SB	Renovate	79	0	111.91	111.96	0.05
Harrison	BROWNS CREEK BRIDGE NB & SB	Renovate	79	0	111.9	111.95	0.05
Harrison	SIXTH STREET BRIDGE	Renovate	1766	0	0	0.48	0.48
Harrison	VIRGINIA AVENUE BRIDGE (LOST CREEK)	Renovate	2138	0	0.021	0.027	0.006
Harrison	WIANT HOLLOW BRIDGE	Replace Superstructure	48	16	0.043	0.049	0.006
Harrison	NUTTERS FARM BRIDGE	Repair or Replace Expansion Joints	1335	0	0.029	0.037	0.008
Harrison	HACKERS CREEK BRIDGE	Replace (due to condition with no added capacity <12')	19	0	0.22	1.39	1.17
Harrison	POINT COMFORT BRIDGE	Repair Substructure	19	0	15.64	17.02	1.38
Harrison	USMC SERGEANT STEPHEN E. DRUMMOND MEMORIAL BRIDGE	Renovate	24	0	6.353	7.39	1.037
Harrison	ELK CREEK WEST	HMA Overlay	50	0	14.64	14.69	0.05
Harrison	BRIDGEPORT HILL OVERPASS	Renovate	50	0	18	18.25	0.25
Harrison	SECOND STREET RAMP	Major Superstructure Repair	50	61	0.01	0.13	0.12
Harrison	CENTER STREET BRIDGE	Replace Bridge (Added Capacity > 12')	1417	0	0.093	0.099	0.006
Jackson	SILVERTON I/C BRIDGE SOUTH & NORTH	Repair or Replace Expansion Joints	77	0	145.96	145.987	0.027
Jackson	SILVERTON I/C BRIDGE SOUTH & NORTH	Repair or Replace Expansion Joints	77	0	145.96	145.99	0.03
Jackson	U.S. ARMY PFC JAMES RAY MILLER MEMORIAL BRIDGE	HMA Overlay	77	0	119.23	119.26	0.03
Jackson	U.S. ARMY PFC JAMES RAY MILLER MEMORIAL BRIDGE	HMA Overlay	77	0	119.23	119.26	0.03
Jackson	WILLIAM S RITCHIE JR	Renovate	33	0	0	0.331	0.331
Kanawha	I-64 SOUTH CHARLESTON ON RAMP D +1	Replace or Renovate Deck	64	0	0	0.366	0.366
Kanawha	US NAVY GM1 SAMUEL H SLACK, JR MEM BR EB PIER	Other Bridge Work	60	0	22.807	22.889	0.082
Kanawha	TYLER CREEK SLAB	Replace (due to condition with no added capacity <12')	62	0	0.31	0.87	0.56
Kanawha	ROCKY FORK CHANNEL BEAM BR	Replace (due to condition with no added capacity <12')	622	0	4.23	5.57	1.34
Kanawha	BOYHOOD HOME OF BOOKER T WASHINGTON	Repair Substructure	77	0	95.81	95.934	0.124
Kanawha	FARNSWORTH DRIVE BRIDGE	Renovate	2137	0	0.155	0.241	0.086
Kanawha	SCHOOL STREET BRIDGE	Replace (due to condition with no added capacity <12')	4591	0	0.015	0.039	0.024
Kanawha	HUBBARD ROAD BRIDGE	Replace Bridge (Added Capacity > 12')	2759	0	0.005	0.011	0.006
Kanawha	SO SIDE CSX RAMP	Renovate	1656	0	0.059	0.127	0.068
Kanawha	CENTRAL AVENUE OVERPASS	Repair Substructure	1069	0	0	1.28	1.28
Kanawha	GEORGE'S CREEK BRIDGE	Replace (due to condition with no added capacity <12')	60	12	6.85	7.23	0.38
Kanawha	MONTROSE DRIVE OVERPASS + 2	Strengthen Substructure or Superstructure	60	64	0.066	0.094	0.028
Kanawha	MONTROSE DRIVE OVERPASS + 2	Strengthen Substructure or Superstructure	60	64	0.155	0.181	0.026

Kanawha	MONTROSE DRIVE OVERPASS + 2	Strengthen Substructure or Superstructure	60	64	0.232	0.268	0.036
Kanawha	FORT HILL BRIDGE RAMP C	Strengthen Substructure or Superstructure	64	0	0	0.408	0.408
Kanawha	I-77 SPRING STREET OVERPASS NB & SB	Repair or Replace Expansion Joints	77	0	101.18	101.18	0
Kanawha	I-77 NB BRIDGE RAMP	Repair or Replace Expansion Joints	77	0	0.55	0.593	0.043
Kanawha	US ARMY SSG HOBERT G. "HOBIE" UNDERWOOD MEMORIAL BR	Repair or Replace Expansion Joints	77	0	106.11	106.17	0.06
Kanawha	US ARMY SSG HOBERT G. "HOBIE" UNDERWOOD MEMORIAL BR	Repair or Replace Expansion Joints	77	0	106.11	106.17	0.06
Kanawha	NEWHOUSE ROAD OVERPASS BR +1	Repair or Replace Expansion Joints	79	0	0.2	0.227	0.027
Kanawha	NEWHOUSE ROAD OVERPASS BR +1	Repair or Replace Expansion Joints	79	0	0.22	0.284	0.064
Kanawha	GREENBRIER UNDERPASS	Renovate	114	0	0.39	0.5	0.11
Kanawha	CHELYAN RAMP BRIDGE	Repair or Replace Expansion Joints	61	0	0.088	0.215	0.127
Kanawha	SOUTH SIDE BRIDGE	Renovate	1025	0	0	0.69	0.69
Kanawha	QUARRIER STREET BRIDGE	Renovate	1038	0	0.979	1.097	0.118
Kanawha	SOUTH RUFFNER SLAB	Renovate	40	0	0.04	0.046	0.006
Kanawha	SCRAGGS DRIVE BRIDGE	Other Bridge Work	4601	0	0.65	0.664	0.014
Lewis	WALKERSVILLE TRUSS	Replace (due to condition with no added capacity <12')	19	0	6.49	6.51	0.02
Lewis	FEAGANS GARAGE BRIDGE	Replace (due to condition with no added capacity <12')	19	0	24.75	24.76	0.01
Lewis	I-79 CO 14/1 O/P MULTI-PLATE ARCH REPLACEMENT +1	Other Bridge Work	79	0	102.3	104.15	1.85
Lewis	CENTER AVENUE BRIDGE +1	Replace Bridge (Added Capacity > 12')	8006	0	0.654	0.666	0.012
Lewis	BLOODY RUN CONCRETE SLAB	Replace (due to condition with no added capacity <12')	7	0	0.23	0.76	0.53
Lewis	OIL CREEK CHANNEL BEAM	Replace (due to condition with no added capacity <12')	23	0	3.75	6.47	2.72
Lewis	PICKLE STREET BOX CULVERT	Drainage/Box Culvert	33	0	1.63	1.635	0.005
Lincoln	US ARMY SP 4 DARRELL GREGORY TRIPLETT MEMORIAL BRIDGE	Replace or Renovate Deck	10	0	28.05	28.29	0.24
Lincoln	BIG CREEK STEEL PLATE ARCH	Replace (due to condition with no added capacity <12')	34	0	0	5.31	5.31
Lincoln	NORTH ALUM CREEK PIPE	Drainage/Box Culvert	12	0	4.91	5.18	0.27
Lincoln	MCCLARITY FORK BRIDGE	Strengthen Substructure or Superstructure	50	1	2.332	2.342	0.01
Logan	US ARMY SPC-4 TOMMY JOE BELCHER MEMORIAL BRIDGE	Replace (due to condition with no added capacity <12')	3	0	3.01	5.91	2.9
Logan	USAM THOMAS MCELWAIN MEM BR	Replace (due to condition with no added capacity <12')	110	20	0.23	0.26	0.03
Logan	SFC TERRANCE N GENTRY MEMORIAL BRIDGE	Repair or Replace Expansion Joints	10	0	8.31	8.66	0.35
Marion	CRANE CREEK NO. 1 +1	Replace Superstructure	5	2	4.153	4.159	0.006
Marion	CRANE CREEK NO. 1 +1	Replace Superstructure	5	2	4.365	4.371	0.006
Marion	TUG TOWER BRIDGE	Replace (due to condition with no added capacity <12')	16	47	0	0.016	0.016
Marion	ACADEMY RD BRIDGE +1	Replace Bridge (Added Capacity > 12')	7	7	0.582	0.586	0.004
Marion	MIDDLETOWN MALL OVERPASS NB	HMA Overlay	79	0	132.07	132.12	0.05
Marion	ALEX ANGELINO MEMORIAL BRIDGE	Repair Substructure	19	0	14.18	14.35	0.17
Marion	MILL FALL I-BEAM	Replace (due to condition with no added capacity <12')	54	0	0.34	1.27	0.93
Marion	COL GEORGE S SPANKY ROBERTS, USAF MEM BR	Repair Substructure	250	0	7.63	7.7	0.07
Marshall	SOUTH IDAMAY ARCH +1	Replace (due to condition with no added capacity <12')	218	0	1.451	1.455	0.004
Marshall	SOUTH IDAMAY ARCH +1	Replace (due to condition with no added capacity <12')	218	0	1.724	1.73	0.006
Marshall	JAMISON NO 9	Replace (due to condition with no added capacity <12')	218	0	5.18	6.9	1.72
Marshall	ELM AVENUE BRIDGE +1	Replace (due to condition with no added capacity <12')	2	26	0.13	0.18	0.05
Marshall	ELM AVENUE BRIDGE +1	Replace (due to condition with no added capacity <12')	495	0	0.391	0.391	0
Marshall	ELM AVENUE BRIDGE +1	Replace (due to condition with no added capacity <12')	495	0	0.383	0.387	0.004
Mason	LEON PIN & LINK BRIDGE	Replace or Renovate Deck	62	0	6.58	6.64	0.06
Mason	WARNER BRANCH	Strengthen Substructure or Superstructure	64	0	4.01	6.77	2.76
Mason	NEW MUD RUN BRIDGE	Renovate	56	0	0.87	0.878	0.008

McDowell	MISSION FARMS ARCH	Replace (due to condition with no added capacity <12')	310	0	0	3.15	3.15
McDowell	POZELL BR	Replace (due to condition with no added capacity <12')	10	0	0.94	0.947	0.007
McDowell	WOLF RUN BR	Replace (due to condition with no added capacity <12')	52	0	1.43	1.436	0.006
McDowell	KAUSOOTH BR	Replace (due to condition with no added capacity <12')	74	2	0	2.71	2.71
McDowell	AVONDALE BR	Replace (due to condition with no added capacity <12')	5	2	4.447	4.487	0.04
McDowell	DAVY ARCH BRIDGE	Replace (due to condition with no added capacity <12')	7	0	5.857	6.61	0.753
McDowell	TWIN BRANCH TRUSS NO 1	Replace (due to condition with no added capacity <12')	7	0	5.2	5.24	0.04
McDowell	SQUIRE ARCH BR	Replace (due to condition with no added capacity <12')	11	0	0	2.01	2.01
McDowell	WAR BRIDGE	Replace or Renovate Deck	16	0	13.39	13.75	0.36
McDowell	WEST HOWARD ST BR	Replace (due to condition with no added capacity <12')	16	48	0	0.054	0.054
Mercer	CAMP CREEK OVERPASS NO. 2 +1	Replace (due to condition with no added capacity <12')	3	0	0.47	0.54	0.07
Mercer	INGLESIDE ROAD BRIDGE	Replace (due to condition with no added capacity <12')	27	0	3.02	3.33	0.31
Mercer	RAY B. CHEATWOOD JR MEM. BRIDGE	Renovate	460	0	13.48	13.518	0.038
Mercer	CAMP CREEK OVERPASS NO. 2 +1	Replace (due to condition with no added capacity <12')	3	0	0.446	0.496	0.05
Mercer	SOUTHBOUND ROCKY HOLLOW BRIDGE	Repair Substructure	77	0	6.92	6.97	0.05
Mercer	EAST END CULVERT	Replace (due to condition with no added capacity <12')	104	0	2.65	2.849	0.199
Mercer	RAY B. CHEATWOOD JR MEM. BRIDGE	Renovate	460	0	13.35	13.53	0.18
Mercer	WICKHAM AVENUE BRIDGE	Replace Superstructure	530	0	0.327	0.335	0.008
Mercer	GARDNER BRIDGE	Replace (due to condition with no added capacity <12')	7	0	3.22	3.32	0.1
Mercer	CAMP CREEK BRIDGE	Replace (due to condition with no added capacity <12')	802	0	0.417	0.425	0.008
Mercer	MASH FORK BRIDGE	Replace Superstructure	801	0	0	0.3	0.3
Mercer	EAST RIVER MOUNTAIN TUNNEL OP	Replace or Renovate Deck	52	0	18.61	18.65	0.04
Mercer	STAFF SERGEANT STANLEY BRIAN REYNOLDS MEMORIAL BRIDGE	HMA Overlay	10	0	0.51	3.91	3.4
Mercer	FRANK S EASLEY BRIDGE	HMA Overlay	52	0	10.62	10.8	0.18
Mineral	FOUNTAIN BRIDGE	Replace Superstructure	16	0	9.93	10.98	1.05
Mineral	NEW CREEK BR	Replace (due to condition with no added capacity <12')	50	0	10.65	10.68	0.03
Mineral	CLAYSVILLE BR	Renovate	93	0	3.42	3.44	0.02
Mineral	CHARLES MILAR BR	Replace (due to condition with no added capacity <12')	10	0	5.36	5.55	0.19
Mineral	BORROR STORE BRIDGE	Replace Superstructure	16	0	0.97	6.05	5.08
Mingo	PVT LAWRENCE OOTEN MEM BR	Replace (due to condition with no added capacity <12')	119	0	20.675	20.779	0.104
Mingo	WILLIAMSON RR OP	Replace Superstructure	15	0	0	3.06	3.06
Mingo	ROBERT H. FOGELSONG BRIDGE	Renovate	119	0	0	0.05	0.05
Mingo	OLD HOUSE BRANCH BR	Replace (due to condition with no added capacity <12')	13	9	0	0.2	0.2
Monongalia	U.S. ARMY SPC JOHN R. TENNANT MEMORIAL BRIDGE	HMA Overlay	7	0	13.09	13.15	0.06
Monongalia	MIRACLE RUN CULVERT	Drainage/Box Culvert	17	1	1.55	2.37	0.82
Monongalia	JOSEPH C. BARTOLO MEMORIAL BRIDGE	Replace or Renovate Deck	19	0	11.08	11.23	0.15
Monongalia	FIELD CREST TIMBER BRIDGE SUPERSTRUCTURE	Replace Superstructure	67	0	7.093	7.101	0.008
Monroe	RAINES CORNER BRIDGE	Replace (due to condition with no added capacity <12')	122	0	10.86	11.89	1.03
Monroe	SECOND CREEK BR	Renovate	219	1	4.62	4.82	0.2
Monroe	INDIAN CREEK BRIDGE	Replace (due to condition with no added capacity <12')	219	0	19.914	19.92	0.006
Morgan	NEW HOPE BR	Replace (due to condition with no added capacity <12')	8	1	3.05	3.13	0.08
Morgan	PALLET FACTORY BRIDGE	Replace (due to condition with no added capacity <12')	13	0	8.07	12.28	4.21
Morgan	SMITH CROSSROAD BR	Replace (due to condition with no added capacity <12')	13	1	1.77	3.07	1.3
Nicholas	HUGHES BRIDGE SB	Replace or Renovate Deck	19	0	7.55	9.63	2.08
Ohio	MORGAN BR	Replace (due to condition with no added capacity <12')	29	0	0.98	0.987	0.007

Ohio	SHILLING BRIDGE	Replace (due to condition with no added capacity <12')	700	0	0.039	0.058	0.019
Ohio	JUNIOR AVENUE BRIDGE	Repair Substructure	481	0	0.009	0.051	0.042
Ohio	28TH STREET BRIDGE	Replace Superstructure	17	0	0.182	0.19	0.008
Ohio	BAKER STREET BRIDGE	Replace (due to condition with no added capacity <12')	8274	0	0.061	2.11	2.049
Ohio	MINE BRIDGE	Replace (due to condition with no added capacity <12')	1	0	2.815	2.855	0.04
Ohio	GERMANY BR	Repair Substructure	40	0	9.1	9.12	0.02
Ohio	WASHINGTON AVENUE BRIDGE	Replace (due to condition with no added capacity <12')	8260	0	0.594	0.594	0
Pendleton	MOUTH OF SENECA BR	Replace (due to condition with no added capacity <12')	28	0	24.07	24.09	0.02
Pendleton	BRIERY GAP BRIDGE	Replace (due to condition with no added capacity <12')	33	0	17.03	19.03	2
Pleasants	BRIDGE STREET BRIDGE	Replace (due to condition with no added capacity <12')	42	0	0.065	0.081	0.016
Pocahontas	THORNY CREEK PARK BRIDGE	Replace or Renovate Deck	28	0	6.33	7.4	1.07
Pocahontas	RILEY RUN BRIDGE	Replace (due to condition with no added capacity <12')	28	0	23.26	26.35	3.09
Pocahontas	2ND ANTHONY CREEK BRIDGE	Renovate	92	0	1.43	1.436	0.006
Preston	BUFFALO CREEK BRIDGE	Replace (due to condition with no added capacity <12')	50	0	14.15	14.18	0.03
Putnam	ARMOUR CREEK BRIDGE	Replace (due to condition with no added capacity <12')	25	0	0.442	0.63	0.188
Putnam	US ARMY CPL ROY E CLARK MEMORIAL BRIDGE	Replace or Renovate Deck	34	0	9.45	9.48	0.03
Putnam	PLYMOUTH BRIDGE	Replace (due to condition with no added capacity <12')	62	0	6.356	6.5	0.144
Putnam	CONNER STREET BRIDGE	Repair Substructure	327	0	0.014	0.024	0.01
Putnam	WAVE POOL BRIDGES	Strengthen Substructure or Superstructure	64	0	34.624	34.65	0.026
Putnam	WAVE POOL BRIDGES	Strengthen Substructure or Superstructure	64	0	34.623	34.649	0.026
Raleigh	PERRY JARRELL BRIDGE	Replace Superstructure	3	5	1.818	1.84	0.022
Raleigh	AMIGO ARCH BRIDGE	Replace Bridge (Added Capacity > 12')	16	0	0.096	0.112	0.016
Raleigh	GLEN MORGAN ARCH	Strengthen Substructure or Superstructure	19	0	13.88	13.88	0
Raleigh	MABSCOTT OVERHEAD BRIDGE +1	Replace Bridge (Added Capacity > 12')	16	0	16.49	16.51	0.02
Raleigh	RHODELL BR NO. 3	Replace (due to condition with no added capacity <12')	33	0	1.312	1.32	0.008
Raleigh	BRECKENRIDGE BRIDGE	Replace Superstructure	99	0	3.65	7.59	3.94
Raleigh	WILLIAM C BROWN BRIDGE	Repair Substructure	19	0	0.034	1.1	1.066
Raleigh	MABSCOTT OVERHEAD BRIDGE +1	Replace Bridge (Added Capacity > 12')	16	0	16.34	16.42	0.08
Raleigh	KNOB HILL OVERPASS	Strengthen Substructure or Superstructure	3	21	0.966	1.83	0.864
Raleigh	JARRELLS BOTTOM BRIDGE	Repair Substructure	902	33	0	0.41	0.41
Randolph	DAVIS AVENUE BRIDGE	Replace (due to condition with no added capacity <12')	2257	0	0.977	0.977	0
Randolph	CORRIDOR H UNDER PASS	Drainage/Box Culvert	33	0	14.84	17.41	2.57
Randolph	DAVIS LICK CULVERT NO. 1	Drainage/Box Culvert	7	0	0	1.56	1.56
Ritchie	SUGAR RUN CULVERT	Drainage/Box Culvert	50	40	2.59	2.93	0.34
Roane	OSBORNE MILLS OVERPASS NBL	Replace or Renovate Deck	79	0	23.15	23.18	0.03
Roane	COOKMAN FORK CULVERT N	Drainage/Box Culvert	79	0	34.05	36	1.95
Taylor	LIBERTY STREET BRIDGE	Renovate	273	0	0.011	0.021	0.01
Tyler	DEEP VALLEY BR	Replace (due to condition with no added capacity <12')	56	0	0	0.92	0.92
Upshur	STAFF SERGEANT LESLEY WAYNE REED US ARMY MEMORIAL BRIDGE	Replace (due to condition with no added capacity <12')	9	0	0.21	0.71	0.5
Upshur	EDEN W-BEAM	Replace (due to condition with no added capacity <12')	46	4	0	0.95	0.95
Upshur	MIDDLE FORK RIVER TRUSS	Replace (due to condition with no added capacity <12')	5	26	0	0.05	0.05
Upshur	BRUSHY FORK ARCH	Major Superstructure Repair	12	0	4.71	5.06	0.35
Wayne	BRINKLEY BRIDGE	Replace or Renovate Deck	152	0	30.64	31.3	0.66
Wayne	ECHO BEAM SPAN	Replace (due to condition with no added capacity <12')	152	0	24.96	24.98	0.02
Wayne	FT GAY TO LOUISA BRIDGE	Repair or Replace Expansion Joints	37	0	0	0.68	0.68

Wayne	PERRY & GENTRY BRIDGE EB +1	Replace or Renovate Deck	64	0	0	1.25	1.25
Wayne	PERRY & GENTRY BRIDGE EB +1	Replace or Renovate Deck	64	0	0	1.232	1.232
Wayne	MISSOURI BRANCH BEAM SPAN	Replace or Renovate Deck	152	0	5.7	5.7	0
Wayne	MIDDLE BRIDGE +1	Major Diamond Grinding with Concrete Pavement Rehab	75	0	7.246	7.284	0.038
Wayne	MIDDLE BRIDGE +1	Major Diamond Grinding with Concrete Pavement Rehab	75	0	9.364	9.412	0.048
Wayne	GRAGSTON CREEK BEAM SPAN	Repair Substructure	52	0	11.022	16	4.978
Webster	MID ERBACON BOX GIRDER +1	Replace (due to condition with no added capacity <12')	9	0	11.638	11.652	0.014
Webster	MID ERBACON BOX GIRDER +1	Replace (due to condition with no added capacity <12')	9	0	11.72	11.727	0.007
Webster	MID ERBACON BOX GIRDER +1	Replace (due to condition with no added capacity <12')	9	0	11.98	11.988	0.008
Webster	CAMDEN ON GAULEY ARCH	Major Superstructure Repair	20	0	0.93	1.03	0.1
Wetzel	DUERNS RUN BRIDGE	Replace Bridge (Added Capacity > 12')	7	0	8.359	8.365	0.006
Wetzel	CAPPO RUN BR	Repair Substructure	69	0	0.461	1.94	1.479
Wetzel	MAIN STREET BRIDGE	Renovate	5501	0	0	2.25	2.25
Wetzel	LT HOWARD R 'BOB' CROTHERS MEMORIAL BR	Repair or Replace Expansion Joints	2	0	5.19	5.24	0.05
Wood	POND CREEK GIRDER (REHAB)	Replace Superstructure	68	0	0	0.046	0.046
Wood	12TH STREET BRIDGE SSDG	Renovate	149	0	0.312	0.316	0.004
Wood	SEN JF DEEM MEM BR	Repair Substructure	68	0	16.629	16.699	0.07
Wood	SEN JF DEEM MEM BR	Repair Substructure	68	0	1.845	1.915	0.07
Wood	SEN JF DEEM MEM BR	Repair Substructure	68	0	16.624	16.731	0.107
Wood	SEN JF DEEM MEM BR	Repair Substructure	68	0	22.73	22.78	0.05
Wood	17TH STREET BRIDGE	Replace Superstructure	189	0	0.349	0.357	0.008
Wyoming	TONEY FORK BRIDGE NO. 1	Replace (due to condition with no added capacity <12')	2	0	0	0.294	0.294
Wyoming	HUFF CREEK BRIDGE NO. 1	Replace (due to condition with no added capacity <12')	8	0	0	1.13	1.13
Wyoming	COON BRANCH BR	Replace (due to condition with no added capacity <12')	9	4	6.658	6.73	0.072
Wyoming	ALLEN JUNCTION ARCH BR	Replace (due to condition with no added capacity <12')	16	0	28.97	29	0.03
Wyoming	MILAM ARCH BRIDGE	Replace (due to condition with no added capacity <12')	5	0	0	4.63	4.63
Wyoming	CAPTAIN CHARLES H. FELLER MEMORIAL BRIDGE	Repair Substructure	54	0	1.25	1.27	0.02